

SUPER-FLEXCOTE

Fast Set Portland Cement Patching and Leveling Compound

1. MANUFACTURER

Super-Tek Products, Inc.

25-44 Borough Place

Woodside, NY 11377 USA

Telephone: (718) 278-7900

Fax: (718) 204-6013

Fax back on Demand: (718) 278-5311

Internet: www.super-tek.com

2. PRODUCT DESCRIPTION

A fast setting polymer-modified, Portland cement patching and leveling compound for preparation of sub-floors prior to floor covering installation. Can be applied from 1/8" to 1/2". Floor covering can be installed in a little as 1 1/2 - 2 hours after application.

- Install floor covering in as little as 1 1/2 hours
- Applications from 1/8" to 1/2"
- High Compressive Strength

3. INSTALLATION

APPROVED SUBSTRATES: All surfaces must be clean and free of dust, grease, wax, and foreign matter. Use over: Fully cured concrete (28 days old), exterior grade plywood (interior floors only), and other underlayment grade substrates.

DO NOT USE OVER: Hardwood, masonite, chipboard, flakeboard, presswood, asbestos board, metal, gypsum based levelers, glass, plastic, cutback adhesive residue, laminate counter tops, or other similarly unstable substrates. Follow floor manufacturer's recommendations for underlayment requirements.

PLEASE NOTE: 1) Do not use to resurface areas that will be left exposed or uncovered. 2) Use two applications (24 hours apart) for fills exceeding 1/2".

MIXING: Add approximately 5 quarts of cool, clean water to 50 lbs. of Super-Flexcote and mix to a thick, paste-like consistency. Use slow speed bucket mixers or mortar box for mixing, do not use high-speed drills. Keep mix times to a minimum. Blend only long enough to attain a smooth, consistent mix. **DO NOT OVER MIX.** Patching compound should be used immediately. **DO NOT** slake, allow to stand, or remix. Mix only an amount that can be used within 15-20 minutes. If mix thickens beyond use **DO NOT** add water and **DO NOT** retemper.

APPLICATION: Use a flat edge steel trowel. Finish the surface to the required smoothness. Do not use at temperatures below 45°F (7°C) or above 95°F (35°C). Jobsite temperature must remain between 45°F and 95°F for a minimum of 72 hours after installation.

CLEAN UP: Freshly mixed Super-Flexcote cleans up with water. If Super-Flexcote hardens, it can only be removed by mechanical abrasion or scraping.

WARNING! EYE AND SKIN IRRITANT. BREATHING DUST MAY CREATE LUNG CANCER RISK. CONTAINS CRYSTALLINE SILICA AND PORTLAND CEMENT. Avoid contact with eyes, skin and clothing. Avoid breathing dust. Wash thoroughly after handling. In case of eye contact, immediately flush with plen-

ty of water for at least 15 minutes, consult a physician immediately. For skin contact, wash affected area with soap and water. For additional information, see Material Safety Data Sheet (MSDS) for this product.

4. COVERAGE:

40 lbs of Super-Flexcote applied at 1/8" thick will cover approximately 40-45 sq. ft.

5. PACKAGING:

40 lb bags. Color: Grey.

6. STORAGE:

Store bags in a cool, dry location out of direct sunlight. Do not store bags on the ground or on concrete. Protect bags from weather and freezing. Shelf life is one year from date of manufacture.

7. NOTICE AND WARRANTY DISCLAIMER:

The MANUFACTURER has provided the enclosed Instructions/Recommendations [I/R] to assist the USER in the application of this product. These I/Rs are not warranted to be comprehensive, complete, thorough or conclusive as regards any specific installation. It is the USER'S obligation to ensure that the product is suitable for it's intended use and that it is compatible with existing conditions or applications of other coincident or adjoining materials. The liability of the SELLER and the MANUFACTURER, whether express or implied, whether in contract or in tort, arising out of warranties, representations, instructions or defects from any cause shall be limited exclusively to replacing the product, provided the same is proved defective, or refunding the purchase price upon return of the unused product. In no event will SELLER or MANUFACTURER be liable for consequential damages, including but not limited to, loss of materials, costs of labor, loss of profits, costs of replacement goods, or other commercial loss. The USER accepts the product AS IS, and without warranties expressed or implied.

8. TECHNICAL ASSISTANCE

Information is available by calling Super-Tek Products:

Mon. thru Fri. (Hours 8:00 AM to 4:30 PM EST)

Telephone: (718) 278-7900 ext. 111

FAX: (718) 204-6013

To receive product information or Material Safety Data Sheets via fax 24 hours 7 days, call: (718) 278-5311